


1000

FIG. 10



1100

FIG. 11

1202

Ln	Car Init	Car Num	Kind of Car	Repair Date	Repaired At	Defect Card Road   Date	Ref Nbr	Acct Dt	Bill Rd
1	DTTX	025093	A - ARTICULATED	3/17/2001	123456 - CHICAGO		711741	2001 - 03	DTLR

1204

Ln	Ref	L	C	APLD	Description	Wheel Information	W	RMVD	Net Charge	
			Qty	C Job   QF		MO YR MF C AS AF RS RF	M Job   QF	R		
2	Mat Dis Olt	A	9	1 4001 00	HTL RUN BD GRATE TYPE 20 IN WIDE		02	4001 00	1	\$148.86
3	NONE		1	3 1311 00	ABD SERVICE PORT. CLEANED &/OR R		12	1311 00	1	\$182.59
4	NONE		3	1 1640 00	BRAKE SHOE-COMP, HI-FRCT 2 IN.		01	1640 00	1	\$41.10
5	NONE	L1	1	3 2616 01	ROLLER BEARING, GROUP 6,6-1/2X12		11	2616 01	1	\$85.17
Total Charge										\$457.72

1206

Ln	Exception Message	Excp Amt	Action
2	CAR NOT EQUIPPED WITH GRATE TYPE RUNNING BOARD.	\$148.86	<input type="radio"/> Allow <input type="radio"/> DisAllow <input type="radio"/> Partial \$

Comments: Refroad comments for Disallow.

Total Exception \$148.86  
BRC Allow | Partial 0.00

Submit/Next Submit

Copyright © 2001 TTX Company. All rights reserved.

FIG. 12

1200 1210 1208

1302

Ln	Car Init	Car Num	Kind of Car	Repair Date	Repaired At	Defect Card Road   Date	Ref Nbr	Acct Dt	Bill Rd
1	DTTX	025093	A - ARTICULATED	3/17/2001	123456 - CHICAGO		711741	2001 - 03	DTLR

1300

Ln	Ref	L	C	APLD	Description	Wheel Information	W	RMVD	Net Charge	
			Qty	C Job   QF		MO YR MF C AS AF RS RF	M Job   QF	R		
2	Mat Dis Olt	A	9	1 4			02	4001 00	1	\$148.86
3	NONE		1	3 1			12	1311 00	1	\$182.59
4	NONE		3	1 1			01	1640 00	1	\$41.10
5	NONE	L1	1	3 2			11	2616 01	1	\$85.17
Total Charge										\$457.72

1304

Exception Comments - Microsoft Internet Explorer

Line Number: 2  
Maximum Characters: 400

Comments  
Refroad Comments for a Disallow

31 Characters Entered

Add Cancel


Copyright © 2001 TTX Company. All rights reserved.

Submit/Next Submit

Copyright © 2001 TTX Company. All rights reserved.

FIG. 13

1302 1300 1304



1400

FIG. 14